

**OUR BEST IN OVERVIEW**

FIND THE SLICING AND PORTIONING MACHINE THAT SUITS YOU!



**PCE KS**

**PCE ES**

**PCE T**

	PCE 70-21 KS	PCE 100-21 KS	PCE 70-25 KS	PCE 100-25 KS	PCE 70-36 KS	PCE 70-21 ES	PCE 100-21 ES	PCE 70-25 ES	PCE 100-25 ES	PCE 70-36 ES	PCE 65 T
<b>Max. input length mm</b>	750	1050	700	1100	700	750	1050	700	1100	700	650
<b>Cross section mm (WxH)</b>	210 x 230	210 x 230	250 x 240	250 x 240	360 x 220	210 x 230	210 x 230	250 x 240	250 x 240	360 x 220	180 x 170
<b>Dimensions mm (LxWxH) (L with conveyor)</b>	1845 x 830 x 1230 (2912)	2495 x 830 x 1230 (3312)	1925 x 950 x 1335 (2990)	2725 x 950 x 1335 (3390)	1925 x 1175 x 1450 (2990)	1845 x 830 x 1387 (2912)	2495 x 830 x 1387 (3312)	1925 x 950 x 1420 (2990)	2725 x 950 x 1420 (3390)	1925 x 1175 x 1450 (2990)	1560 x 670 x 670
<b>Connection (other voltage on request)</b>	400 V / 2,7 kW	400 V / 2,7 kW	400 V / 4,5 kW	400 V / 4,5 kW	400 V / 4,5 kW	400 V / 2,7 kW	400 V / 2,7 kW	400 V / 4,5 kW	400 V / 4,5 kW	400 V / 4,5 kW	400 V / 2,7 kW
<b>Weight kg</b>	240	260	320	360	450	240	260	320	360	450	200
<b>Performance single blade slices/minute</b>	220	220	220	220	220	220	220	220	220	220	180
<b>Performance double blade Slices/minute (continuous)</b>	440	440	440	440	-	440	440	440	440	-	-
<b>Slice thickness mm</b>	1 - 32	1 - 32	1 - 32	1 - 32	1 - 32	1 - 750	1 - 1000	1 - 700	1 - 1000	1 - 700	1 - 32
<b>Slice thickness optional</b>	1 - 50	1 - 50	1 - 50	1 - 50	1 - 50	-	-	-	-	-	-

**FUNCTIONS**

<b>Start device</b>	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
<b>Flap start</b>	-	-	-	-	-	✓	✓	✓	✓	✓	-
<b>Return limiter</b>	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
<b>Distribution of remaining slice</b>	-	-	-	-	-	✓	✓	✓	✓	✓	-
<b>Slicing software</b>	-	-	-	-	-	✓	✓	✓	✓	✓	-
<b>Reinforced drive system</b>	-	-	✓	✓	-	-	-	✓	✓	-	-
<b>Conveyor belt</b>	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	-
<b>Adjustable gripper</b>	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	-